



LENNAR ORLANDO


Reunion Village – 40's Product

Reunion Village 40's

Plan 2382 Columbia

2370sf

5 Bed – 2 ½ Bath – 2-Car



Reunion Village 40's

Plan 2382 Columbia



Elevation – H

Elevation – J



Reunion Village 40's

Plan 3014
Alexander Palm
3014sf
5 Bed – 5 Bath – 1-Car



Reunion Village 40's

Plan 3014 Alexander Palm

Elevation – D1M

Elevation – D2M





Reunion Village 40's

Plan 3275 Majesty Palm

3275sf

6 Bed – 5 Bath – 1-Car



Reunion Village 40's

Plan 3275 Majesty Palm

Elevation – D1M

Elevation – D2M



My Contact Information:

Tony Webb

Director of Product Development

Ph. 352.459.3702

tony.webb@lennar.com



Elevation "D1M"

Elevation "C" - Modern

Elevation "D2M"